

Inspection Report

Report No.: XYWD-140705
Supplier : XY-GLOBAL

Inspection Date: 28th July, 2014
Inspector: Leo

Inspection only for: PO . XYWD-140705 Item No. XY31SY49	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY49	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

6. report

[illegible]