XY-GLOBAL **XY Electronics Technology Co., Ltd**

Inspection Report

Report No.: XYCY-150303 **Inspection Date:** 25th Mar, 2015
Supplier : **XY-GLOBAL** **Inspector:** Leo

Inspection only for:	Inspection Result:
PO . XYCY-150303 Item No. XY31CY005	**PASS**

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY005	**3000PCS**	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:

6. report

□□□□□	CNC□□ □□□□□□□□□CNC□□□□□□□□□□□□□□□□□□ □□□□□□□□□CNC□□□□□□□□□CNC□□□□□□□CNC □□□□□CNC□□□□□□□□□CNC□□□□□□□□□□□
□□	□□□□□□ AL6061 AL6065□AL6063□AL7075□ SUS304□SUS303□SUS316□POM□□
□□□	□□□□□ □□□□□□□
□□□□	□ □□□□□□□□□□□□□□ □□□□□□□□□□□□□□□□□□□□□
□□□□□	□□ □□□□□□□□□□□□□□□□□□□
□□□□	CNC □□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□□□□□CNC□□□ □
□□□□□□	□□ □□□□□□□□□□□□gague□□□□□□□□□□□□□□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□□□□□□□