

Inspection Report

Report No.: XYNK-140514
Supplier : XY-GLOBAL

Inspection Date: 7th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYNK-140514 Item No.40010870	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
40010870	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

Company Name	Shenzhen Hengsheng Technology Co., Ltd. OEM/ODM service available
Product Name	ADC12/A380
Material	ADC12/A380
Surface Treatment	Electroplating / Anodizing / Polishing
Process	CNC Machining / Turning / Milling
MOQ	1000 pieces
Lead Time	15-20 days
Payment Terms	T/T, L/C, Western Union
Quality Control	ISO 9001:2015 certified
Shipping Method	By Air / By Sea
1.Name	Shenzhen Hengsheng Technology Co., Ltd. OEM/ODM service available
2.Process	CNC Machining / Turning / Milling
3.Material	ADC12/A380
4.Surface	Electroplating / Anodizing / Polishing
5.Tolerance	±0.01mm
6.Quantity	1000 pieces
7.Specification	OEM/ODM service available
8.Delivery Time	15-20 days
9.Payment Terms	T/T, L/C, Western Union
10.Certification	Austrian EU
11.ISO 9001	ISO 9001:2015 certified
12. Quality Control	ISO 9001:2015 certified
13. Shipping Method	By Air / By Sea
14. OEM/ODM	OEM/ODM service available