

□□A380□□□□□□□□□□

Inspection Report

Report No.: XYS-130711
Supplier : XY-GLOBAL

Inspection Date: 10th Aug, 2013
Inspector: Leo

Inspection only for: PO : XYS-130711 Item No.XY-3519400	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-3519400	4000PCS	5% inspection	0pcs	No failure	4000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

ชื่อ	บริษัท. จำกัดOEM
ประเภท	ADC12A380
ชื่อ	ชื่อ
ชื่อ	ชื่อ
ชื่อ	CNC
ชื่อ	CNC
ชื่อ	ชื่อ
MOQ	ชื่อ
ชื่อ/ชื่อ	+/- 0.01
ชื่อ	T / T 50T / T
ชื่อ	CNC
ชื่อ	ชื่อ
ชื่อ	ชื่อ
ชื่อ	20-25&NBSP T / T 50
ชื่อ	ชื่อ
1.Name	บริษัท. จำกัดOEM
2.Process	CNC
3.	ADC12A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	accessoried
10.	AustrialEU
11&NBSP	ISO 9001
ชื่อ	
1	ISO10
2.	
3	surefacefinishmentkindlsavailable
	4
5.	
	6
7.	
	&NBSP
	ISO9001
	OEM