

Inspection Report

Report No.: XYNK-130809

Supplier : XY-GLOBAL

Inspection Date:14th Sep-, 2013

Inspector:LEO

Inspection only for:	Inspection Result:
PO : XYNK-130809 Item No.400-10-200	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-10-200	3000PCS	100% inspection	0pcs	No failure	3000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

[illegible]