

## Inspection Report

Report No.: XYD-131025

Supplier : XY-GLOBAL

Inspection Date: 19<sup>th</sup> Nov-, 2013

Inspector: ALEX

|                                                                |                                   |
|----------------------------------------------------------------|-----------------------------------|
| Inspection only for:<br>PO . XYD-131025    Item No. XY-MST-082 | <u>Inspection Result:</u><br>PASS |
|----------------------------------------------------------------|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY-MST-082  | 80000PCS      | 1% inspection | 0pcs         | No failure          | 80000pcs        |

### Appearance Inspection :

No failure,

### Dimension Inspection:

No failure , below measurement report for reference.

### Assembly Test:

No failure

### Inspection Summary

The inspection sample plan is 100% inspection.

### Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]