

Inspection Report

Report No.: XYI-140317
Supplier : XY-GLOBAL

Inspection Date: 13th Apr, 2014
Inspector: Leo

Inspection only for: PO . XYI-140317 Item No.142150	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
142150	20000PCS	1% inspection	Opcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing




2. Product



3. Product



4 Product



5. Product:

po-dmis		4000-01-1000	10.00.00.00	10.00.00.00
NO	10.00	10.00	10.00	10.00
1	10.00	10.00	10.00	10.00
2	10.00	10.00	10.00	10.00
3	10.00	10.00	10.00	10.00
4	10.00	10.00	10.00	10.00
5	10.00	10.00	10.00	10.00
6	10.00	10.00	10.00	10.00
7	10.00	10.00	10.00	10.00
8	10.00	10.00	10.00	10.00
9	10.00	10.00	10.00	10.00
10	10.00	10.00	10.00	10.00
11	10.00	10.00	10.00	10.00
12	10.00	10.00	10.00	10.00
13	10.00	10.00	10.00	10.00
14	10.00	10.00	10.00	10.00
15	10.00	10.00	10.00	10.00
16	10.00	10.00	10.00	10.00
17	10.00	10.00	10.00	10.00
18	10.00	10.00	10.00	10.00
19	10.00	10.00	10.00	10.00
20	10.00	10.00	10.00	10.00
21	10.00	10.00	10.00	10.00
22	10.00	10.00	10.00	10.00
23	10.00	10.00	10.00	10.00
24	10.00	10.00	10.00	10.00
25	10.00	10.00	10.00	10.00
26	10.00	10.00	10.00	10.00
27	10.00	10.00	10.00	10.00
28	10.00	10.00	10.00	10.00
29	10.00	10.00	10.00	10.00
30	10.00	10.00	10.00	10.00
31	10.00	10.00	10.00	10.00
32	10.00	10.00	10.00	10.00
33	10.00	10.00	10.00	10.00
34	10.00	10.00	10.00	10.00
35	10.00	10.00	10.00	10.00
36	10.00	10.00	10.00	10.00
37	10.00	10.00	10.00	10.00
38	10.00	10.00	10.00	10.00
39	10.00	10.00	10.00	10.00
40	10.00	10.00	10.00	10.00
41	10.00	10.00	10.00	10.00
42	10.00	10.00	10.00	10.00
43	10.00	10.00	10.00	10.00
44	10.00	10.00	10.00	10.00
45	10.00	10.00	10.00	10.00
46	10.00	10.00	10.00	10.00
47	10.00	10.00	10.00	10.00
48	10.00	10.00	10.00	10.00
49	10.00	10.00	10.00	10.00
50	10.00	10.00	10.00	10.00
51	10.00	10.00	10.00	10.00
52	10.00	10.00	10.00	10.00
53	10.00	10.00	10.00	10.00
54	10.00	10.00	10.00	10.00
55	10.00	10.00	10.00	10.00
56	10.00	10.00	10.00	10.00
57	10.00	10.00	10.00	10.00
58	10.00	10.00	10.00	10.00
59	10.00	10.00	10.00	10.00
60	10.00	10.00	10.00	10.00
61	10.00	10.00	10.00	10.00
62	10.00	10.00	10.00	10.00
63	10.00	10.00	10.00	10.00
64	10.00	10.00	10.00	10.00
65	10.00	10.00	10.00	10.00
66	10.00	10.00	10.00	10.00
67	10.00	10.00	10.00	10.00
68	10.00	10.00	10.00	10.00
69	10.00	10.00	10.00	10.00
70	10.00	10.00	10.00	10.00
71	10.00	10.00	10.00	10.00
72	10.00	10.00	10.00	10.00
73	10.00	10.00	10.00	10.00
74	10.00	10.00	10.00	10.00
75	10.00	10.00	10.00	10.00
76	10.00	10.00	10.00	10.00
77	10.00	10.00	10.00	10.00
78	10.00	10.00	10.00	10.00
79	10.00	10.00	10.00	10.00
80	10.00	10.00	10.00	10.00
81	10.00	10.00	10.00	10.00
82	10.00	10.00	10.00	10.00
83	10.00	10.00	10.00	10.00
84	10.00	10.00	10.00	10.00
85	10.00	10.00	10.00	10.00
86	10.00	10.00	10.00	10.00
87	10.00	10.00	10.00	10.00
88	10.00	10.00	10.00	10.00
89	10.00	10.00	10.00	10.00
90	10.00	10.00	10.00	10.00
91	10.00	10.00	10.00	10.00
92	10.00	10.00	10.00	10.00
93	10.00	10.00	10.00	10.00
94	10.00	10.00	10.00	10.00
95	10.00	10.00	10.00	10.00
96	10.00	10.00	10.00	10.00
97	10.00	10.00	10.00	10.00
98	10.00	10.00	10.00	10.00
99	10.00	10.00	10.00	10.00
100	10.00	10.00	10.00	10.00

6. Report:

品名	铝合金精密加工零件. 根据客户要求定制各种规格零件OEM加工
材料	ADC12/A380
规格	根据客户要求
数量	根据客户要求
表面处理	阳极氧化/喷粉/喷漆
公差	±0.01mm
交期	CNC加工周期5-10天
包装	气泡膜+珍珠棉+木箱
MOQ	1000个
价格	+/- 0.01元/个
付款方式	T / T 50%定金, 50%尾款
工厂	CNC加工中心
地址	深圳市宝安区西乡街道
电话	0755-26000000
邮箱	20-25@163.com
网站	www.1688.com
1.Name 铝合金精密加工零件OEM加工	
2.Process CNC加工	
3.材料 ADC12/A380	
4.Surface 阳极氧化/nickle	
5.Tolerance ±0.01mm	
6.数量 1000个	
7.Specification OEM加工	
8.交期 25-30天	
9.包装 气泡膜+珍珠棉+木箱	
10.认证 Austrial/EU	
11&NBSP; ISO 9001	
铝合金精密加工零件	
ISO 9001:2015	
2. 表面处理	
3. surface finishment kinds available	
4. 数量	
5. 交期	
6. 包装	
7. 认证	
铝合金精密加工零件	
20-25&NBSP; ISO 9001	
OEM加工	