

□□□□□□□□□□□□□□□□

Inspection Report



Report No.: XYS-130324
Supplier : XY-GLOBAL

Inspection Date: 20th Apr, 2013
Inspector: Leo

Inspection only for: PO . XYS-130324 Item No.XY-1302870	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1302870	500PCS	10% inspection	0pcs	No failure	500pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

ชื่อ	บริษัท ฟูจิยามา จำกัด
ชื่อสินค้า	ADC12 A380
ชื่อ	ชื่อ
ชื่อ	ชื่อ
ชื่อ	ชื่อ
ชื่อ	CNC
ชื่อ	ชื่อ
MOQ	ชื่อ
ชื่อ/ชื่อ	+/- 0.01
ชื่อ	T / T 50% T / T
ชื่อ	CNC
ชื่อ	ชื่อ
ชื่อ	ชื่อ
ชื่อ	20-25 T / T 50%
ชื่อ	ชื่อ
1.Name	OEM
2.Process	CNC
3.	ADC12 A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	accessoried
10.	Austrial EU
11&NBSP	ISO 9001
ชื่อ	
ISO	1 10
2.	
3 sureface	finishment kinds available
ชื่อ	4
5.	
ชื่อ	6
7.	
ชื่อ	
ชื่อ	&NBSP
ชื่อ	
ชื่อ	ISO9001
ชื่อ	
OEM	