

applied

Inspection Report

Report No.: XYS-130315
Supplier : XY-GLOBAL

Inspection Date: 12th Apr, 2013
Inspector: Leo

Inspection only for: PO . XYS-130315 Item No.XY-1300270	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1300270	1000PCS	5% inspection	0pcs	No failure	1000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	铝合金 压铸机OEM
规格	ADC12/A380
材质	铝合金
重量	约 100kg
产地	中国 广东 东莞
品牌	CNC
表面处理	阳极氧化
MOQ	100
交货期	+/- 0.01mm
包装	T / T 50% T / T 50%
付款方式	CNC 压铸机OEM
售后服务	1. 24小时技术支持 2. 终身保修
其他	20-25% T / T 50%
备注	1. 24小时技术支持 2. 终身保修
1.Name	铝合金 压铸机OEM
2.Process	CNC
3.规格	ADC12/A380
4.Surface	阳极氧化
5.Tolerance	+/- 0.01mm
6.重量	100kg
7.Specification	OEM
8.交货期	25-30天
9.付款方式	accessoried
10.包装	Austrial EU
11.&NBSP	ISO 9001
品名	铝合金 压铸机OEM
规格	100kg
2.重量	100kg
3.sureface	finishment kinds available
4.重量	100kg
5.重量	100kg
6.重量	100kg
7.重量	100kg
品名	铝合金 压铸机OEM
规格	100kg
2.重量	100kg
3.sureface	finishment kinds available
4.重量	100kg
5.重量	100kg
6.重量	100kg
7.重量	100kg
品名	铝合金 压铸机OEM
规格	100kg
2.重量	100kg
3.sureface	finishment kinds available
4.重量	100kg
5.重量	100kg
6.重量	100kg
7.重量	100kg