

Inspection Report


Report No.: XYGA-150321
Supplier : XY-GLOBAL

Inspection Date: 23th Apr., 2015
Inspector: LEO

Inspection only for: PO : XYGA-140321 Item No. XY21ZC058	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC058	10000pcs	7% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

[illegible]