

Inspection Report

Report No.: XYSK-140612

Supplier : XY-GLOBAL

Inspection Date: 5th- July, 2014

Inspector: Leo

Inspection only for: PO . XYSK-140612 Item No. XY31SY012	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY012	18000PCS	1% inspection	Opes	No failure	18000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

6. report

	CNC
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 5050T / T;
	CNC CNC CNC
	CNC
	20-25T / T 50
	CNC
1.NameOEM CNC	
2.ProcessCNC	
3.MaterialAL6061 AL6065AL6063AL7075 POM	
4.Surfacenickle	
5.Tolerance+/- 0.01	
6100	
7.SpecificationOEMserice	
8.2530	
9.CNC accessoried	
10.AustrialEU	
11.ISO 9001	
ISO1. 10	
2.	
3. surefacefinishmentkindlsavailable	
4.	
5.	
6.	
7.	
CNC	
CNC	
CNCISO9001	
CNC	
CNCOEM	