

□□□□□□□□□□□□□□□□

Inspection Report

Report No.: 130925

Inspection Date: 25th Sep 2013

Supplier :

Inspector: Ken Tung

Inspection only for: Item No. ARM00039	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
ARM	1000sets	100%	12pcs	12pcs poor painting	1000pcs

Appearance Inspection :

No failure,

12pcs poor painting

Dimension Inspection:

No failure , below measurement report for reference.

Leakage Test:

No failure

Inspection Summary

The inspection sample plan are follow AQL , 12pcs poor painting The result of inspection is acceptable.

Digital photo records :



1. Packing

2. Product




3. Product

4. Item number




5. Product

6. Product



7 Customer No.

8. Product



9. Defect-Poor painting

10. Defect-Poor painting



11. Test

12. Test



13. Carton

14. Loading

ชื่อ	บริษัท ออโต้แมติก เทคโนโลยี จำกัด OEM/ODM
ผลิตภัณฑ์	ADC12/A380
ชื่อ	ชื่อ บริษัท
ที่อยู่	เลขที่ ถนน ตำบล อำเภอ จังหวัด
โทรศัพท์	โทรศัพท์มือถือ
อีเมล	CNC
MOQ	MOQ
ราคา/ชิ้น	+/- 0.01
สี	T / T 50% T / T
วัสดุ	CNC
การรับประกัน	การรับประกัน
ชื่อ	ชื่อ
ชื่อ	20-25&NBSP T / T 50
ชื่อ	ชื่อ
1.Name	OEM
2.Process	CNC
3.ผลิตภัณฑ์	ADC12/A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.ขนาด	100
7.Specification	OEM
8.ขนาด	25-30
9.การรับประกัน	accessoried
10.การรับประกัน	Austrial/EU
11&NBSP	ISO 9001
ชื่อ	
ISO	10
2.การรับประกัน	
3.sureface/finishment	kindls/abailable
การรับประกัน	4
5.การรับประกัน	
การรับประกัน	6
7.การรับประกัน	
ชื่อ	
การรับประกัน&NBSP	
การรับประกัน	
การรับประกัน	ISO9001
การรับประกัน	
OEM	