

Inspection Report


Report No.: XYN-140517
Supplier : XY-GLOBAL

Inspection Date: 12th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYN-140517 Item No.XY-140430	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-140430	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

	OEM
	ADC12A380
	CNC
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50
	CNC
	20-25T / T 50
1.Name	OEM
2.Process	CNC
3.	ADC12A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	accessoried
10.	AustrialEU
11&NBSP	ISO 9001
ISO	110
2.	
3.sureface	finishmentkindlsavailable
	4
5.	
	6
7.	
&NBSP	
	ISO9001
OEM	