

Inspection Report

Report No.: XYKI-140323
Supplier : XY-GLOBAL

Inspection Date: 19th Apr, 2014
Inspector: Leo

Inspection only for: PO : XYKI-140323 Item No.2400170	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
2400170	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

品名	铝合金 铝制精密零件OEM
规格	ADC12/A380
数量	10000
用途	汽车零部件
材料	铝合金
工艺	CNC 精密加工
表面处理	阳极氧化
MOQ	1000
公差	+/- 0.01mm
交期	T / T 50% 50% T / T
包装	CNC 精密加工
备注	
1.Name	铝合金 铝制精密零件OEM
2.Process	CNC 精密加工
3.Material	ADC12/A380
4.Surface	阳极氧化
5.Tolerance	+/- 0.01mm
6.	10000
7.Specification	OEM
8.	25/30
9.	accessoried
10.	Austrial/EU
11.	ISO 9001
品名	
ISO	1. 10
2.	
3. sureface	finishment kinds available
4.	
5.	
6.	
7.	
8.	
9.	
10.	
11.	
12.	
13.	
14.	
15.	
16.	
17.	
18.	
19.	
20.	
21.	
22.	
23.	
24.	
25.	
26.	
27.	
28.	
29.	
30.	
31.	
32.	
33.	
34.	
35.	
36.	
37.	
38.	
39.	
40.	
41.	
42.	
43.	
44.	
45.	
46.	
47.	
48.	
49.	
50.	
51.	
52.	
53.	
54.	
55.	
56.	
57.	
58.	
59.	
60.	
61.	
62.	
63.	
64.	
65.	
66.	
67.	
68.	
69.	
70.	
71.	
72.	
73.	
74.	
75.	
76.	
77.	
78.	
79.	
80.	
81.	
82.	
83.	
84.	
85.	
86.	
87.	
88.	
89.	
90.	
91.	
92.	
93.	
94.	
95.	
96.	
97.	
98.	
99.	
100.	