

Inspection Report

Report No.: XYN-140613

Supplier : XY-GLOBAL

Inspection Date: 7th July, 2014

Inspector: Leo

Inspection only for: PO : XYN-140613 Item No.213098	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
213098	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

6. Report:

[illegible]