

Inspection Report

Report No.: XYWD-140621
Supplier : XY-GLOBAL

Inspection Date: 15th July, 2014
Inspector: Leo

Inspection only for: PO : XYWD-140621 Item No. XY31SY38	<u>Inspection Result:</u> PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY38	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report

Product Name: XY31SY38 Part No: XY31SY38 Inspection Date: 2014.7.15

Inspector: Leo Inspected: Leo Inspected Date: 2014.7.15

Inspection Result: PASS

Inspection Method: 100% inspection

Inspection Item: 1. Appearance 2. Dimension 3. Assembly

Inspection Result: 1. Appearance: PASS 2. Dimension: PASS 3. Assembly: PASS

Inspection Summary: The inspection sample plan is 100% inspection.

Inspector: Leo Inspected: Leo Inspected Date: 2014.7.15

5. Product:

6. report

[illegible]