

Inspection Report

Report No.: XYCY-150302

Inspection Date: 25th Mar, 2015

Supplier: XY-GLOBAL

Inspector: Leo

Inspection only for: PO: XYCY-150302 Item No. XY31CY004	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY004	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

6. report

[illegible]