

Inspection Date: 15th July, 2014
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY33AH014	32000PCS	1% inspection	Opes	No failure	32000pcs

The inspection sample plan is 100% inspection.

Three stacked cardboard boxes, each labeled "XY-GLOBAL". The boxes are brown and appear to be shipping containers. They are stacked vertically on a light-colored floor. The top box is slightly offset to the right. The middle and bottom boxes are slightly offset to the left. The background is a plain, light-colored wall.

2. Product



4 Product

[illegible]

6. report

[illegible]