

Inspection Date: 10th July, 2014
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY34	30000PCS	1% inspection	Opes	No failure	30000pcs

The inspection sample plan is 100% inspection.



2. Product



4 Product

[illegible]

6. report

[illegible]