

□□□□□□□□□□A380□□□□□□□□□□□□□□□□LED

Inspection Report



Report No.: XYS-130717
Supplier : XY-GLOBAL

Inspection Date: 15th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130717 Item No.XY-2524960	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-2524960	1000PCS	5% inspection	0pcs	No failure	1000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

ชื่อ	บริษัท ออโต้แมติกแมชีน จำกัด OEM/ODM
วัสดุ	ADC12/A380
รูป	รูป
ขนาด	ขนาด
สี	สี
ผิว	CNC
MOQ	MOQ
ราคา	+/- 0.01
เวลา	T / T 50% T / T 50%
สถานที่	CNC
การรับประกัน	การรับประกัน
การขนส่ง	การขนส่ง
การชำระเงิน	20-25% T / T 50%
การติดต่อ	การติดต่อ
1.Name	บริษัท ออโต้แมติกแมชีน จำกัด
2.Process	CNC
3.วัสดุ	ADC12/A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.ขนาด	100
7.Specification	OEM
8.การรับประกัน	25-30
9.การชำระเงิน	accessoried
10.การติดต่อ	Austrial/EU
11&NBSP	ISO 9001
การติดต่อ	
1 ISO	10
2	
3 sureface	finishment
4	
5	
6	
7	
การติดต่อ	
&NBSP	
การติดต่อ	
ISO9001	
การติดต่อ	
OEM	