

ADC12

Inspection Report

Report No.: XYS-130911
Supplier : XY-GLOBAL

Inspection Date: 4th Oct, 2013
Inspector: Leo

Inspection only for: PO . XYS-130911 Item No.500017	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
500017	5000PCS	5% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

ชื่อ	บริษัท ออโต้แมติก เทคโนโลยี จำกัด OEM/ODM
ประเภท	ADC12/A380
สี	สีเงิน
ขนาด	ขนาด 100mm
วัสดุ	ADC12
กระบวนการ	CNC
MOQ	1000
ราคา/ชิ้น	+/- 0.01
ระยะเวลา	T / T 50% T / T 50%
การรับประกัน	CNC 1 ปี
การขนส่ง	ทางเรือ
เอกสาร	ใบรับรอง ISO 9001
1.Name	บริษัท ออโต้แมติก เทคโนโลยี จำกัด
2.Process	CNC
3.ประเภท	ADC12/A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.ขนาด	100mm
7.Specification	OEM/ODM
8.ระยะเวลา	25-30 วัน
9.การขนส่ง	ทางเรือ
10.การรับประกัน	Austrial/EU
11&NBSP	ISO 9001
ISO	1000
2.การขนส่ง	ทางเรือ
3.sureface	finishment
4.การขนส่ง	ทางเรือ
5.การขนส่ง	ทางเรือ
6.การขนส่ง	ทางเรือ
7.การขนส่ง	ทางเรือ
การขนส่ง	ทางเรือ
การขนส่ง	ทางเรือ
การขนส่ง	ทางเรือ
การขนส่ง	ทางเรือ
OEM	1000