

Inspection Report

Report No.: XYK-140517
Supplier : XY-GLOBAL

Inspection Date: 12th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYK-140517 Item No.XY-141708	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-141708	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product




3. Product



4 Product



5. Product:



6. Report:

[illegible]