



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYK-131022
Supplier : XY-GLOBAL

Inspection Date: 18th Nov-, 2013
Inspector: ALEX

Inspection only for: PO . XYK-131022 Item No.XY-CT-D-085	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-CT-D-085	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]