

Inspection Report

Report No.: XYWD-140612
Supplier : XY-GLOBAL

Inspection Date: 7th July, 2014
Inspector: Leo

Inspection only for: PO : XYWD-140612 Item No. XY31SY32	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY32	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co., Ltd	
Date: 2014.07.07 PO: XYWD-140612 Part: XY31SY32 Lot: 140612-01 Inspector: Leo	Product Name: XY31SY32 Lot: 140612-01 Inspector: Leo
Inspection Item: 1. Appearance 2. Dimension 3. Assembly Test 4. Function Test 5. Reliability Test 6. Environmental Test 7. Safety Test 8. Performance Test 9. Compatibility Test 10. Interference Test 11. Electromagnetic Compatibility Test 12. Thermal Test 13. Vibration Test 14. Shock Test 15. Humidity Test 16. Salt Crystallization Test 17. Corrosion Test 18. Wear Test 19. Fatigue Test 20. Life Test	
Inspection Result: 1. Appearance: Pass 2. Dimension: Pass 3. Assembly Test: Pass 4. Function Test: Pass 5. Reliability Test: Pass 6. Environmental Test: Pass 7. Safety Test: Pass 8. Performance Test: Pass 9. Compatibility Test: Pass 10. Interference Test: Pass 11. Electromagnetic Compatibility Test: Pass 12. Thermal Test: Pass 13. Vibration Test: Pass 14. Shock Test: Pass 15. Humidity Test: Pass 16. Salt Crystallization Test: Pass 17. Corrosion Test: Pass 18. Wear Test: Pass 19. Fatigue Test: Pass 20. Life Test: Pass	
Inspection Summary: The inspection sample plan is 100% inspection.	
Inspection Report No.: XYWD-140612-01	

5. Product:

6. report

[illegible]