

Inspection Report


Report No.: XYK-130904
Supplier : XY-GLOBAL

Inspection Date: 29th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYK-130904 Item No. Stainless steel sheet	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Stainless steel sheet	3000PCS	5% inspection	0pcs	No failure	3000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 5% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

	CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
	+/- 0.01
	T / T 50 T / T;
	CNC CNC CNC CNC
	CNC
	20-25 T / T 50
	CNC
1.Name OEM CNC	
2.ProcessCNC	
3.AL6061 AL6065AL6063AL7075POM	
4.Surfacenickle	
5.Tolerance+/- 0.01	
6100	
7.SpecificationOEM	
825-30	
9CNCaccessoried	
10AustrialEU	
11 ISO 9001	
ISO110	
2	
3 surefacefinishmentkindlsavailable	
4	
5	
6	
7	
CNC&NBSP	
CNC	
CNCISO9001	
CNC	
CNCOEM	