

Inspection Report

Report No.: XYR-130813

Supplier : XY-GLOBAL

Inspection Date:1th Sep-, 2013

Inspector:LEO

Inspection only for: PO . XYR-130813 Item No.1420214	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1420214	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing




2. Product:




3. Product:



4. Product:



5. Product :



6. Product:

[illegible]