

Inspection Report

Report No.: XYWD-140702
Supplier : XY-GLOBAL

Inspection Date: 28th July, 2014
Inspector: Leo

Inspection only for: PO . XYWD-140702 Item No. XY31SY48	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY48	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

[illegible]