

Inspection Report

Report No.: XYS-130831
Supplier : XY-GLOBAL

Inspection Date: 11th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYS-130831 Item No. Fishing gear wheel	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Fishing gear wheel	30PCS	100% inspection	30pcs	No failure	30pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product:	4. Product
	
5. Product :	6. Product:

	CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316POM
	&NBSP
	CNC
	gague
MOQ	
/	+/- 0.01
T / T	5050T / T
	CNC CNC CNC CNC
	CNC
	nickle
	+/- 0.01
	100
	7.Specification OEM
	25-30
	9CNC accessoried
	Austrial EU
	11&NBSP ISO 9001
	ISO 110
	2
	3 sureface finishment kinds available
	4
	5
	6
	7
	CNC &NBSP
	CNC
	CNC ISO9001
	CNC
	CNC OEM