

□ □

Inspection Report

Report No.: XYS-130729
Supplier : XY-GLOBAL

Inspection Date: 20th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130729 Item No.XY-1302130	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1302130	2000PCS	5% inspection	0pcs	No failure	2000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

ชื่อ	บริษัท ออโต้แมติก เทคโนโลยี จำกัด OEM/ODM
วัสดุ	ADC12/A380
รูป	รูป
ขนาด	ขนาด
สี	สี
ผิว	CNC
MOQ	MOQ
ราคา	+/- 0.01
เวลา	T / T 50% T / T
สถานที่	CNC
การรับประกัน	การรับประกัน
การขนส่ง	การขนส่ง
การชำระเงิน	20-25% T / T 50%
การติดต่อ	การติดต่อ
1.Name	บริษัท ออโต้แมติก เทคโนโลยี จำกัด OEM/ODM
2.Process	CNC
3.วัสดุ	ADC12/A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.ขนาด	100
7.Specification	OEM/ODM
8.การรับประกัน	25-30
9.การชำระเงิน	accessoried
10.การติดต่อ	Austrial/EU
11&NBSP	ISO 9001
ISO	10
2	
3 sureface	finishment
4	
5	
6	
7	
ISO	
ISO	
ISO	9001
OEM	