

Inspection Report

Report No.: XYI-140315
Supplier : XY-GLOBAL

Inspection Date: 12th Apr, 2014
Inspector: Leo

Inspection only for: PO . XYI-140315 Item No.142140	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
142140	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. Report:

品名	铝合金精密压铸加工件OEM
材料	ADC12/A380
数量	
用途	
表面处理	
加工精度	CNC
交货期	gague
MOQ	
公差	+/- 0.01
交期	T / T 50
包装	CNC
检验标准	
备注	
尺寸	20-25 T / T 50
重量	
1.Name 铝合金OEM	
2.Process CNC	
3.材料ADC12/A380	
4.Surface 铝合金nickle	
5.Tolerance +/- 0.01	
6.数量100	
7.Specification OEM	
8.交货期25-30	
9.配件accessoried	
10.认证Austrial EU	
11&NBSP;ISO 9001	
ISO	
ISO 10	
2	
3 sureface finishment kinds available	
4	
5	
6	
7	
ISO	
&NBSP;	
ISO	
ISO 9001	
OEM	