

Inspection Report

Report No.: XYGA-150320

Supplier : XY-GLOBAL

Inspection Date: 23th Apr-, 2015

Inspector: LEO

Inspection only for: PO . XYGA-140320 Item No. XY21ZC057	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC057	8000pcs	7% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product:



3. Product:

4. Product:

[illegible]

5. Product :

6. Inspection report:

