

Inspection Report

Report No.: XYAN-150315

Supplier : XY-GLOBAL

Inspection Date: 19th- Apr-, 2015

Inspector:LEO

Inspection only for: PO . XYBA-150315 Item No. XY21ZC102	<u>Inspection Result:</u> PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC102	12000pcs	7% inspection	0pcs	No failure	12000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product:



3. Product:

4. Product:

[illegible]

5. Product :

6. Inspection report:

[illegible]

Safety is our serious job for our worker and engineer team

