

Inspection Report

Report No.: XYSL-130509

Supplier : XY-GLOBAL

Inspection Date: 8th Jun, 2013

Inspector: Leo

Inspection only for: PO . XYSL-130509 Item No. XY11SL005	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL005	3000PCS	5% inspection	Opcs	No failure	3000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product

[illegible]

5. Product:

6. The test report

[illegible]