

Inspection Report

Report No.: XYBA-140901

Inspection Date: 18th Oct., 2014

Supplier: XY-GLOBAL

Inspector: LEO

Inspection only for:	Inspection Result:
PO: XYBA-140901 Item No. XY21ZC001	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC001	1000PCS	7% inspection	0pcs	No failure	1000pcs

Appearance Inspection:
No failure,
Dimension Inspection:
No failure, below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records:

1. Packing

2. Product:

3. Product:

4. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection	Product type	Inspection Date	Inspector
XY21ZC001	XY21ZC001	18/10/2014	LEO
Inspection Item	Inspection Result	Inspection Method	Inspection Standard
Appearance	Pass	Visual	XY21ZC001
Dimension	Pass	Caliper	XY21ZC001
Assembly	Pass	Visual	XY21ZC001
Function	Pass	Visual	XY21ZC001
Material	Pass	Visual	XY21ZC001
Label	Pass	Visual	XY21ZC001
Storage	Pass	Visual	XY21ZC001
Transportation	Pass	Visual	XY21ZC001
Disposal	Pass	Visual	XY21ZC001
Recycling	Pass	Visual	XY21ZC001
Other	Pass	Visual	XY21ZC001

5. Product:

6. Inspection report:

	CNC
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50 50T / T;
	CNC CNC CNC CNC
	CNC
	20-25T / T 50
	CNC
1.Name	OEM CNC
2.Process	CNC
3.Material	AL6061 AL6065AL6063AL7075 POM
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEMserice
8.	2530
9.	CNC accessoried
10.	AustrialEU
11.	ISO 9001
ISO	1. 10
2.	
3. sureface	finishment kindsavailable
	4.
5.	
	6.
7.	
CNC	
CNC	
CNC	ISO9001
CNC	
CNC	OEM