

Inspection Report

Report No.: XYN-140604
Supplier : XY-GLOBAL

Inspection Date: 2nd July, 2014
Inspector: Leo

Inspection only for: PO : XYN-140604 Item No.100583	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
100583	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product




5. Product:



6. Product::



5. Product:



6. Report:

[illegible]