

CNC□□□□□□

Inspection Report

Report No.: XYK-131011
Supplier : XY-GLOBAL

Inspection Date: 29th Oct-, 2013
Inspector: LEO

Inspection only for: PO . XYK-131011 Item No. connector	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
connector	3000SET	5% inspection	0pcs	No failure	3000SET

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 5% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

	CNC CNC CNC CNC
	AL6061 AL6065AL6063AL7075 &NBSP; SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
	+/- 0.01
	T / T 50 50T / T;
	CNC CNC CNC CNC
	CNC
	20-25&NBSP;T / T 50
	CNC
1.Name	OEM CNC
2.Process	CNC
3.	AL6061 AL6065AL6063AL7075POM
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	CNCaccessoried
10.	AustrialEU
11&NBSP;	ISO 9001
ISO	110
2.	
3	surefacefinishmentkindlsavailable
	4
5.	
	6
7.	
CNC&NBSP;	
CNC	
CNC	ISO9001
CNC	
CNC	OEM