

Inspection Report

Report No.: XYSL-140614

Supplier : XY-GLOBAL

Inspection Date: 19th Jul, 2014

Inspector: Leo

Inspection only for:	<u>Inspection Result:</u>
PO , XYSL-140614 Item No. XY11WD038	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD038	18000PCS	5% inspection	0pcs	No failure	18000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

[illegible]

5. Product:

6. The test report

[illegible]