



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYJ-131015

Supplier : XY-GLOBAL

Inspection Date: 9th Nov-, 2013

Inspector: LEO

Inspection only for:

PO : XYJ-131015 Item No. XY-CT-D-060

Inspection Result:

PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-CT-D-060	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing




2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]