

Inspection Report

Report No.: XYSL-140610

Supplier : XY-GLOBAL

Inspection Date: 10th Jul, 2014

Inspector: Leo

Inspection only for: PO . XYSL-140610 Item No. XY11WD034	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD034	10000PCS	5% inspection	Opes	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product

[illegible]

5. Product:

6. The test report

