

□□A380□□□□□□□□□□□□□□□□

Inspection Report

Report No.: XYS-130711
Supplier : XY-GLOBAL

Inspection Date: 10th Aug, 2013
Inspector: Leo

Inspection only for: PO : XYS-130711 Item No.XY-3519400	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-3519400	4000PCS	5% inspection	0pcs	No failure	4000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

品名	铝合金 压铸机OEM
规格	ADC12/A380
材质	铝合金
重量	约 100kg
精度	±0.01mm
表面处理	阳极氧化
MOQ	100台
交货期	20-25天
包装	木箱包装
认证	ISO 9001
其他	