

Inspection Report

Report No.: XYSS-131010
Supplier: XY-GLOBAL

Inspection Date: 25th Nov., 2013
Inspector: LEO

Inspection only for: PO . XYSS-131010 Item No. Cylinder_FirstAid	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Cylinder_FirstAid	6PCS	100% inspection	0pcs	No failure	6pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 50pcs inspection.

Digital photo records :	
	
1. Packing	2. Packing
	
3. Product:	4. Product:
	
5. Product :	6. Product:

	CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316POM
	&NBSP
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50T / T
	CNC CNC CNC CNC
	CNC
	20-25&NBSP T / T 50
	CNC
1.Name OEM CNC	
2.Process CNC	
3.AL6061 AL6065AL6063AL7075POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6.100	
7.Specification OEM	
8.25-30	
9.CNC accessoried	
10.Austrial EU	
11&NBSP ISO 9001	
ISO110	
2	
3 sureface finishment kinds available	
4	
5	
6	
7	
CNC &NBSP	
CNC	
CNC ISO9001	
CNC	
CNC OEM	