

Inspection Report

Report No.: XYD-140508
Supplier : XY-GLOBAL

Inspection Date: 6th Jun, 2014
Inspector: Alex

Inspection only for: PO . XYD-140508 Item No.XY-1415249	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1415249	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

The table contains multiple rows of data with columns for various measurements and tolerances. The data is organized in a structured format typical of a CMMI report.

6. Report:

ชื่อ	บริษัท อดิเรก จำกัด
ชื่อสินค้า	ADC12 A380
ชื่อ	ชื่อ
ชื่อ	ชื่อ
ชื่อ	CNC
ชื่อ	CNC
ชื่อ	CNC
MOQ	MOQ
ชื่อ/ชื่อ	+/- 0.01
ชื่อ	T / T 50% T / T
ชื่อ	CNC
ชื่อ	ชื่อ
ชื่อ	ชื่อ
ชื่อ	20-25 T / T 50
ชื่อ	ชื่อ
1.Name	บริษัท อดิเรก จำกัด
2.Process	CNC
3.	ADC12 A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	accessoried
10.	Austrial EU
11&NBSP	ISO 9001
ชื่อ	ชื่อ
ISO	1 10
2.	ชื่อ
3.sureface	finishment kinds available
ชื่อ	4
5.	ชื่อ
ชื่อ	6
7.	ชื่อ
ชื่อ	ชื่อ
ชื่อ	&NBSP
ชื่อ	ชื่อ
ชื่อ	ISO9001
ชื่อ	ชื่อ
OEM	ชื่อ