

Inspection Report



Report No.: XYI-140314
Supplier : XY-GLOBAL

Inspection Date: 10th Apr, 2014
Inspector: Leo

Inspection only for: PO . XYI-140314 Item No.141030	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
141030	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	铝合金压铸件OEM
材料	ADC12/A380
数量	
用途	
表面处理	
加工精度	CNC
公差	gague
MOQ	
交期	+/- 0.01
包装	T / T 50
备注	CNC
其他要求	
图片	
尺寸	20-25 T / T 50
重量	
1.Name 铝合金OEM	
2.Process CNC	
3.材料ADC12/A380	
4.Surface 铝合金nickle	
5.Tolerance +/- 0.01	
6.数量100	
7.Specification OEM	
8.重量25-30	
9.配件accessoried	
10.认证Austrial EU	
11&NBSP;ISO 9001	
ISO	
ISO 110	
2	
3 sureface finishment kinds available	
4	
5	
6	
7	
ISO	
&NBSP;	
ISO9001	
OEM	