

Inspection Report

Report No.: XYDA-150307
Supplier: XY-GLOBAL

Inspection Date: 3th Apr, 2015
Inspector: Leo

Inspection only for: PO . XYDA-150307 Item No. XY31CY026	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY026	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.


Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

[illegible]