

Inspection Report


Report No.: XYN-140622
Supplier : XY-GLOBAL

Inspection Date: 17th July, 2014
Inspector: Leo

Inspection only for: PO . XYN-140622 Item No.302698	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
302698	15000PCS	1% inspection	0pcs	No failure	15000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

	CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50 50T / T:
	CNC CNC CNC CNC
	20-25 T / T 50
	CNC
	1.Name OEM CNC
	2.Process CNC
	3. AL6061 AL6065AL6063AL7075POM
	4.Surface nickle
	5.Tolerance +/- 0.01
	6 100
	7.Specification OEM
	8 25-30
	9 CNC accessoried
	10 Austrial EU
	11 ISO 9001
	ISO 1 10
	2
	3 sureface finishment kindls abailable
	4
	5
	6
	7
	CNC &NBSP
	CNC
	CNC ISO9001
	CNC
	CNC OEM