

Inspection Report

Report No.: XYA-130205
Supplier : XY-GLOBAL


Inspection Date: 24th Apr., 2013
Inspector:KEN

Inspection only for:	Inspection Result:
Item No: CA241-0208	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
CA241-0208	320000 PCS	500PCS	5pcs	No failure, with little flaws, acceptable	320000pcs

Appearance Inspection :
5pcs burrs and scratch on products surface, acceptable
Dimension Inspection:
No failure , refer to measurement report.
Assembly Test:
No failure
Inspection Summary
The inspection sample is 100% inspection.

Digital photo records :



ชื่อ	CNC ทั่วไป CNC ทั่วไป CNC ทั่วไป CNC ทั่วไป
ชื่อ	อลูมิเนียม AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
ชื่อ	ทั่วไป
ชื่อ	ทั่วไป
ชื่อ	ทั่วไป
ชื่อ	CNC ทั่วไป
ชื่อ	ทั่วไป
MOQ	ทั่วไป
ชื่อ/ชื่อ	+/- 0.01mm
ชื่อ	T / T 50 T / T 50 T / T 50
ชื่อ	CNC ทั่วไป CNC ทั่วไป CNC ทั่วไป
ชื่อ	ทั่วไป CNC ทั่วไป
ชื่อ	ทั่วไป
ชื่อ	20-25 T / T 50
ชื่อ	CNC ทั่วไป
1.ชื่อ OEM CNC ทั่วไป	
2.ชื่อ CNC ทั่วไป	
3.Material AL6061 AL6065 AL6063 AL7075 POM	
4.ชื่อ	
5.ชื่อ ±0.01mm	
6.ชื่อ 100	
7.ชื่อ OEM service	
8.ชื่อ 25-30	
9.ชื่อ CNC ทั่วไป	
10.ชื่อ Austria EU	
11.ชื่อ ISO 9001	
ชื่อ	
1. ISO 10	
2.ชื่อ	
ชื่อ	
4.ชื่อ	
5.ชื่อ	
6.ชื่อ	
7.ชื่อ	
ชื่อ	
CNC ทั่วไป	
CNC ทั่วไป	
CNC ทั่วไป ISO9001	
CNC ทั่วไป	
CNC ทั่วไป OEM ทั่วไป	
ชื่อ	