

Inspection Report

Report No.: XYL-150722

Inspection Date: 5th Sep, 2015

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYL-150722 Item No. XY11LM022	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM022	16000PCS	1% inspection	Opes	No failure	16000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product

[illegible]

5. Product:

6. Report:

	OEM
	ADC12A380
	CNC
	gague
MOQ	
	+/- 0.01
	T / T 50T / T
	CNC
	2025 T / T 50
1.Name OEM	
2.Process CNC	
3.Material ADC12A380	
4.Surface	
5.Tolerance +/- 0.01	
6 100	
7.Specification OEM serice	
8 25-30	
9 accessoried	
10 Austrial EU	
11.ISO 9001	
1 ISO10	
2	
3 surefacefinishmentkindlsavailable	
4	
5	
6	
7	
ISO9001	
OEM	

Safety is our serious job for our worker and engineer team

