

Inspection Date: 28th July, 2014
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY47	90000PCS	1% inspection	0pcs	No failure	90000pcs

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



Figure 1 shows a 12-pin D-sub connector. The top view displays the pin arrangement with labels for Pin 1 through Pin 12. The side view shows the connector's profile. The drawing is labeled 'XK-YC03B' and 'XK-YC03B'.

5. Product:

6. report

[illegible]