

Inspection Report

Report No.: XYDA-150318
Supplier : XY-GLOBAL

Inspection Date: 10th Apr, 2015
Inspector: Leo

Inspection only for: PO . XYDA-150318 Item No. XY31CY035	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY035	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure


Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing




2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report Form

Product Name: XY31CY035 Part No: XY31CY035 Inspection Date: 10/04/2015 Inspector: Leo

Customer: XYDA-150318 Qty: 30000PCS Lot No: XYDA-150318-001

Inspection Method: 100% Sampling Method: 100%

Inspection Result: PASS

Defects Found: 0 Defects Description: No failure

Acceptable Quality: 30000PCS

Inspection Summary: The inspection sample plan is 100% inspection.

Signature: Leo Date: 10/04/2015

6. report

[illegible]