

Inspection Report

Report No.: XYL-150724
Supplier : XY-GLOBAL

Inspection Date: 12th Sep, 2015
Inspector: Leo

Inspection only for:	<u>Inspection Result:</u>
PO . XYL-150724 Item No. XY11LM024	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM024	18000PCS	1% inspection	Opes	No failure	18000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure - below measurement report for reference

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product

[illegible]

5. Product:

6. Report:

[illegible]

Safety is our serious job for our worker and engineer team

